




U.I. Lapp GmbH  
Schulze Delitzsch Straße 25 D 70565 Stuttgart  
www.lappgroup.com

## Anbaussteckverbinder, gerade

EPIC® LS1.5 A1 3+PE+2  
EPIC® LS1.5 A1 3+PE+4




NICHT UNTER LAST STECKEN ODER TRENNEN  
NOT FOR CURRENT INTERRUPTION  
NE PAS UTILISER POUR COUPER LE COURANT

- Litzen an Kontakte crimpen und durch den Haltering Pos. 1 schieben.
- Kontakte seitlich in Isolierkörper-Unterteil Pos. 2 einclippen.
- Isolierkörper-Unterteil Pos. 2 mit konfektionierten Kontakten in die Isolierhülse Pos. 3 schieben.
- Einheit Pos. 2 und Pos. 3 in das Gehäuse Pos. 4 einführen.
- Haltering Pos. 1 in das Gehäuse Pos. 4 montieren.
- Flanschsteckereinheit mit Schrauben Pos. 5 an der Montagewand befestigen.

Panel base connectors,  
straight

EPIC® LS1.5 A1 3+PE+2  
EPIC® LS1.5 A1 3+PE+4



NIHT UNTER LAST STECKEN ODER TRENNEN  
NOT FOR CURRENT INTERRUPTION  
NE PAS UTILISER POUR COUPER LE COURANT

- Crimp the conductors to the contacts and push them through the support (1).
- Clip the contacts into the lower part of the insulating body (2).
- Slice the lower part of the insulating body (2) with the assembled contacts into the insulating sleeve (3).
- Guide the unit (2) and (3) into the housing (4).
- Mount the support (1) in the housing (4).
- Secure flange connector unit to the mounting panel using screws (5).