

SCP110






Installation

Condensation switch
Kondensationsvakt
Kondensationswächter
Countroleur de condensation
Interruptor de condensacion
Interruttore di condensazione

Instruction
Montageanvisning
Bedienungsanleitung
Instructions d'installation
Instrucciones de empleo
Istruzioni per installazioni

Schneider Electric

CE



6.
Attention! Unscrew terminal block before connecting wires.
OBS! Lossa plinnskruven innan du ansluter.
Achtung! Vor dem Anschließen Klemmblock lösen.
Attention! Avant la connexion bornier dissoudre.
Atencion! Antes de conectar suelte el bloque de terminals.
Attenzione! Prima di connettere avvitare il morsetto.

SCP110

Installation

Condensation switch
Kondensationsvakt
Kondensationswächter
Countroleur de condensation
Interruptor de condensacion
Interruttore di condensazione

Instruction
Montageanvisning
Bedienungsanleitung
Instructions d'installation
Instrucciones de empleo
Istruzioni per installazioni

Schneider
Electric



部件名称 Part Name	有害物质 - Hazardous Substances					
	铅 (Pb)	汞 (Hg)	镉 (Cd)	六价铬 (Cr (VI))	多溴联苯 (PBB)	多溴二苯醚 (PBDE)
金属部件 Metal parts	○	○	○	○	○	○
塑料部件 Plastic parts	○	○	○	○	○	○
电子件 Electronic	X	○	○	○	○	○
触点 Contacts	○	○	○	○	○	○
线缆和线缆附件 Cables & cabling accessories	○	○	○	○	○	○

本表格依据SJ/T11364的规定编制。

O: 表示该有害物质在该部件所有均质材料中的含量均在GB/T 26572规定的限量要求以下。

X: 表示该有害物质至少在该部件的某一均质材料中的含量超出GB/T 26572规定的限量要求。

(企业可在此处, 根据实际情况对上表中打的技术原因进行进一步说明。)



This table is made according to SJ/T 11364.

O: indicates that the concentration of hazardous substance in all of the homogeneous materials for this part is below the limit as stipulated in GB/T 26572.

X: indicates that concentration of hazardous substance in at least one of the homogeneous materials used for this part is above the limit as stipulated in GB/T 26572