



	230 V <sub>~</sub>
	12 mA
	50 Hz
	2 x 2,5 mm <sup>2</sup>
$x =$	$x = 12$
	4 x ( $\varnothing 0,6 \text{ mm} < \frac{8 \text{ mm}}{x} < \varnothing 0,8 \text{ mm}$ )
	-5°C → +45°C

230 V <sub>~</sub>	4 x 400 W	4 x 1,7 A	4 x 400 W	4 x 1,7 A	4 x 400 W	4 x 1,7 A






[www.legrandoc.com](http://www.legrandoc.com)

