


CE6323	INSTALLATION GUIDE
Valid from: 06.10.2020	RJ45 plug Stewart (Stewart) Cat.5 GY

Installation Guide



Push the boot onto the patch cable. Cut the patch cable at a right angle.



Strip the cable approx. 25mm. The shielding foil must not be damaged.



Remove the foil over the wires. Shorten the braiding by 5mm and put it back on the jacket.



A ring is pushed over the pairs of wires until it stops at the jacket. The wire pairs are now arranged side by side according to the pin assignment and pushed into the guide comb approx. 15mm. Shorten the wires to the required length.



Before crimping, the guide comb must be pressed firmly into the sleeve. It should hardly be visible afterwards. The plug lies tightly against the ring.



Now the ring is crimped, making sure that the wires are connected to the contacts and the plug is tightly fitted to the ring.



Then the boot is pushed over the plug until it locks into place.